



08 9387 3888

A. 59 Pangbourne St, Wembley, 6014
(Chr of Grantham St & Pangbourne St)
E. service@wembleyautocare.com.au
ABN. 11 602 546 681

DATE: 11/11/2024


TAX INVOICE: [REDACTED]
TO: [REDACTED]

VEHICLE DETAILS

MAKE: JEEP WRANGLER
PLATE: [REDACTED]
ODO: 193,123 kms

DETAILS

QUANTITY



INVESTIGATE

The customer has reported check tie rod ends. A senior mechanic has investigated and found the boots are split on ball joints but there is no major play there. Not urgent.

INVESTIGATE

The customer has reported handbrake not working properly. DO NOT USE - NEEDS TO PARK IN GEAR WITH HANDBRAKE OFF. A senior technician has investigated and recommends having this diagnosed correctly.

INVESTIGATE

The customer has reported 1st gear pops out. A senior mechanic has investigated and suspects the gearbox may need to be rebuilt. Refer to a transmission specialist. (Referral below).

INVESTIGATE

The customer has reported drivers window not working. A senior mechanic has investigated and found there is no power at the plug for the motor but there is a clicking sound audible from the switch. The wiring has been tampered with where it goes to the door. Refer to auto electrician. (Referral below).

INVESTIGATE

The customer has reported check rear main oil seal. A senior mechanic has investigated and found it has an extremely heavy leak. May need a new clutch also. The ideal time to have this done would be with the transmission rebuild at gearbox specialist.

INVESTIGATE

The customer has reported check drive shaft coupling. A senior mechanic has investigated and found the coupling seemed in serviceable condition.

INVESTIGATE

The customer has reported earth straps - one at top fine - one that goes from engine to chassis is frayed and it has been tied on. A senior mechanic has investigated and found the lower earth strap requires replacing.

INVESTIGATE

The customer has reported a leak coming from transmission. A senior mechanic has investigated and found it is the rear main seal leaking, not the transmission.

INVESTIGATE

The customer has reported electronics not working properly. A senior mechanic has investigated and found all of the electronics need to be inspected by an auto electrician.



WAITING TO REPAIR





☎ 08 9387 3888

A. 59 Pangbourne St, Wembley, 6014
(Chr of Grantham St & Pangbourne St)

E. service@wembleyautocare.com.au
ABN. 11 602 546 681

DETAILS

QUANTITY

AMOUNT

INVESTIGATE

The customer has reported this car had a scan - right rear wheel - (implausible right wheel signal received) and right rear wheel speed sensor - ABS light on dash - couldn't clear codes. A senior mechanic has investigated and found the sensor was not plugged in properly. Our scan tools will not connect properly. Refer to auto electrician.


INVESTIGATE

The customer has asked to check battery. A senior mechanic has investigated and found the battery is fine.

NOTE

The suspension needs attention. The right hand rear tyre is rubbing on the sway bar when suspension is moving up and down. refer to Pedders.

Our care and commitment to you - FREE



NEEDS ATTENTION

DETAILS

GENERAL REPAIR

Diagnose hand brake issue.

GENERAL REPAIR - AVAILABLE OVERSEAS - PREPAYMENT REQUIRED

Remove and replace lower engine earth strap. Test operation.

Perth Gearbox Differential & Clutch Centre


135 Great Eastern Hwy,
Rivervale
WA 6103,
(08) 9277 2344

REFER TO AUTO ELECTRICIAN

Innovation Auto Electrical
Mobile Electrician
Edward Williams
innovation.auto.electrical@proton.me
0413255368

REFER TO TO SUSPENSION SPECIALIST

Pedders Suspension & Brakes
56 Collingwood St, Osborne Park WA 6017
(08) 9244 9544





☎ 08 9387 3888

A. 59 Pangbourne St, Wembley, 6014
(Cnr of Grantham St & Pangbourne St)

E. service@wembleyautocare.com.au
ABN. 11 602 546 681

DETAILS

QUANTITY

AMOUNT

THANK YOU FOR LETTING US LOOK AFTER YOU AND YOUR CAR.



and we'll give you both \$25 off your next Cobalt Blue Comprehensive Service as a way of saying thanks.